proflor h

VINYL FLOOR SEALER



Uses

For sealing of vinyl floors.

Application

Applied using a mop or polish applicator. 1-3 coats can be applied to the floor surface. Before application, ensure that the floor is free from dirt and that any previous treatments to the floor have been removed using the appropriate polish stripper.

Dilution

Use undiluted.

Supplies

5lt container - P07105

20lt container - P07100

Storage

Protect from sunlight and do not expose to temperatures exceeding 50°C. Sensitive to frost.

Compounds

- Polymers
- Waxes
- Plasticizers
- Preservatives

Hazardous components

None

Technical specifications

| Description | Result |
|--------------------------|---------------|
| Colour | Milky |
| pH in concentrate | 8.5 ± 0.5 |
| Specific gravity at 20°C | 1.030 g/ml |
| Total solids | 21% |

Specifications and details are subject to change without prior notice

Industroclean (Pty) Ltd Tel: +27 11 801 4600

Mail: info@industroclean.co.za www.industroclean.co.za

proflor h VINYL FLOOR SEALER



Common problems

| Problem | Cause | Remedy |
|-------------------------|--|---|
| Low gloss | Improper floor preparation | Use recommended stripper |
| | Porous substrate | Seal floors |
| | Poor recoat | Allow polish to dry completely |
| Hazing | Environmental conditions | Allow longer drying times under high humidity. Light buffing to removing "Ghosting" |
| | Incompatibility with the substrate or sealer | Check compatibility. Only use polishes and sealers that are recommended. |
| Levelling | Residue on the floor | Strip and wash floors to remove any contaminants. |
| | Insufficient plasticizer and wetting agent in polish | Add more plasticizer and wetting aid to polish. |
| Tackiness | Inadequate drying | Allow longer drying times between coats. |
| Water spotting | Too much wetting agent | Reduce wetting agent |
| | Inadequate plasticizer | Increase level or type of plasticizer |
| Powdering | Poor film formation | Increase plasticizer or coalescent. |
| Premature loss of gloss | Contamination of substrate | Strip and clean floor |
| Swirling | Equipment | Check buff pad, speed and pressure. |
| | Polish may not be suitable for buffing | Use a buffable wax in formula |
| Dirt pick up | Soft polish | Reduce coalescent and plasticizer. |